

Employee Suggestion - [REDACTED] No. 218

25X1A9a

A. Information about the Suggestor:

25X1A9a

[REDACTED], GS-11, Mechanical Engineer, TSS

25X1A6a

B. Summary of the Suggestion:

The suggestor proposes that the location of certain clothing hooks in rest rooms of [REDACTED] and anywhere else the condition exists be relocated to provide for employee safety.

C. Present Location:

At present clothing hooks are fastened to the top of the door, however, because of the location in such close quarters it is a safety hazard in that an employee may be subjected to head or eye injuries in striking his head upon the hooks.

D. Location:

The suggestor recommends that clothing hooks be placed on the right side of booths thus preventing accidents or injuries to the head or eyes.

E. Estimated Savings:

No monetary savings can be estimated as any benefits such as avoidance of compensation cases or loss of employee services due to sick leave are intangible in nature.

F. Evaluation:

The Chief, General Services Office recognizes the validity of the suggestion and has reported that arrangements are being made to relocate these clothing hooks at the earliest possible time.

G. Note:

The Committee may desire to consider a token award for this safety suggestion which is provided for in the Guide to Scale of Awards For Suggestions Providing Intangible Benefits.